



# INDUSTRIAL CASE STUDY

## HELICOPTER DECK PROTECTION



### SITUATION

An aluminum helicopter deck was in need of repair. The current coating was flaking and peeling. A more permanent solution was needed that would not flake and crack under the harsh conditions from being located out at sea.



### SOLUTION

What was left of the existing coating had to be sand blasted, steamed cleaned and then primed. The key to all successful LINE-X industrial applications is a well prepared surface. Once the surface was fully prepared, LINE-X XS-100 was sprayed across 210 m2 of the helicopter pad area. The whole area was completed in 4 hours and was able to be walked upon within 5-10 seconds.



### RESULTS

The helicopter deck was returned to service within one day. The LINE-X XS-100 coating will not crack, split or warp under the extreme weather changes and it is also durable enough to withstand the foot traffic and continual landing and taking-off of a helicopter.

**PROJECT OVERVIEW:** Damage Resistant Floor Lining For Helicopter Pad

**PRODUCTS USED:** LINE-X XS-100



[WWW.LINEXAUS.COM.AU](http://WWW.LINEXAUS.COM.AU)